

ISO/TS 13399-309:2016-03 (E)

Cutting tool data representation and exchange - Part 309: Creation and exchange of 3D models - Tool holders for indexable inserts

Contents		Page
Foreword		vi
Introduction		viii
1	Scope	1
2	Normative references	1
3	Starting elements, coordinate systems, planes	2
3.1	General	2
3.2	Reference system (PCS -- primary coordinate system)	2
3.3	Tool item position	2
3.3.1	Prismatic tool position	3
3.3.2	Round tool position	3
3.4	Planes	4
3.5	Cutting reference point (CRP)	5
3.6	Design of the pocket seat	8
3.7	Adjustment coordinate system on workpiece side	12
3.7.1	General	12
3.7.2	Designation of the coordinate system workpiece side	12
4	Design of the model	14
4.1	Necessary parameters for the connection interface feature	14
4.2	Necessary properties for insert and pocket seat	15
4.2.1	General	15
4.2.2	Properties for equilateral, equiangular and equilateral, non- equiangular inserts	15
4.2.3	Properties for non-equilateral, equiangular and non-equilateral, non- equiangular inserts	15
4.2.4	Properties for round inserts	16
4.2.5	Design of the pocket seat feature	16
5	Tool holder for longitudinal and transversal turning	17
5.1	General	17
5.2	Necessary properties	17
5.3	Basic geometry	18
5.4	Turning tool with pocket seat and top surface offset	21
5.5	Turning tool assembly	21
5.6	Boring bar body	22
6	Turning tool for external threading	24
6.1	General	24
6.2	Necessary properties	24
6.3	Basic geometry	25
6.4	Turning tool with pocket seat and top surface offset	25
6.5	Turning tool assembly	26
7	Boring bar for internal threading	27
7.1	General	27
7.2	Necessary properties	27
7.3	Basic geometry	28
7.4	Boring bar with pocket seat and top surface offset	29
7.5	Boring bar assembly	30

8	Turning tool for OD grooving and parting	30
8.1	General	30
8.2	Necessary properties	30
8.3	Basic geometry	32
8.4	Grooving tool with pocket seat and top surface offset	33
8.5	Grooving and cut-off tool assembly	33
9	Boring bar for ID grooving	34
9.1	General	34
9.2	Necessary properties	34
9.3	Basic geometry	35
9.4	Boring bar with pocket seat and top surfaces	36
9.5	Grooving boring bar assembly	37
10	Pull back boring bar	37
10.1	General	37
10.2	Necessary properties	38
10.3	Basic geometry	38
10.4	Boring bar with pocket seat and top surfaces	39
10.5	Pull back boring bar assembly	39
11	System tool for external turning	40
11.1	General	40
11.2	Necessary properties	40
11.3	Basic geometry	41
11.4	System tool with pocket seat and top surfaces	41
11.5	Assembly of system tool for external turning	42
12	System tool for external threading	43
12.1	General	43
12.2	Necessary properties	43
12.3	Basic geometry	44
12.4	System tool with pocket seat and top surfaces	44
12.5	Assembly of a system tool for external threading	44
13	System tool for internal turning	44
13.1	General	44
13.2	Necessary properties	45
13.3	Basic geometry	45
13.4	System tool with pocket seat and top surfaces	45
13.5	System tool for internal turning assembly	45
14	System tool for internal threading	46
14.1	General	46
14.2	Necessary properties	46
14.3	Basic geometry	46
14.4	System tool with pocket seat and top surfaces	46
14.5	System tool for internal threading assembly	46
15	System tool for OD grooving and/or cut-off	47
15.1	General	47
15.2	Necessary properties	47
15.3	Basic geometry	48
15.4	Grooving tool with pocket seat and top surface offset	48
15.5	System tool for OD grooving and parting assembly	48
16	System tool for ID grooving	49
16.1	General	49
16.2	Necessary properties	49
16.3	Basic geometry	49

16.4	Grooving tool with pocket seat and top surface offset	49
16.5	System tool for ID grooving assembly	49
17	Pull back system tool	50
17.1	General	50
17.2	Necessary properties	50
17.3	Basic geometry	50
17.4	System tool with pocket seat and top surfaces	51
17.5	Pull back system tool assembly	51
18	System tool, neutral design for OD turning	51
18.1	General	51
18.2	Necessary properties	51
18.3	Basic geometry	52
18.4	System tool with pocket seat and top surfaces	52
18.5	System tool, neutral design for OD turning assembly	52
19	Design of details	52
19.1	Basics for modelling	52
19.2	Fixing threads for inserts	52
19.3	Contact surfaces/drive keys -- Orientation	52
19.4	Chamfers and roundings	52
20	Attributes of surfaces -- Visualization of the model features	52
21	Structure of the design elements (tree of model)	53
22	Data exchange model	54
Annex A (normative) Mirror planes for left-handed tools		56
Annex B (informative) Information about nominal dimensions		57
Bibliography		58