

# ISO/TS 13399-70:2016-07 (E)

## Cutting tool data representation and exchange - Part 70: Graphical data layout - Layer setting for tool layout

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3</b>	<b>Layer concept .....</b>	<b>4</b>
<b>4</b>	<b>Structure of the layers .....</b>	<b>5</b>
4.1	General .....	5
4.2	Colouring of the layers .....	5
4.3	Grouping and definition of the layers .....	6
4.3.1	Grouping .....	6
4.3.2	Basic layer .....	6
4.3.3	Tool drawing (main view -- function number 3.0.1) .....	6
4.3.4	NC-Geometry (CUT, NOCUT -- function number 3.0.2) .....	8
4.3.5	Extended tool drawing (further views -- function number 3.0.3) .....	9
4.3.6	Multilingual (global drawing -- function number 3.0.4) .....	10
4.3.7	Tool reconditioning (supplier specific information -- function number 3.0.5) .....	12
4.3.8	Machine equipment layout (machining processes -- function number 3.0.6) .....	13
4.3.9	Drawing frame (multilingual and drawing space -- function number 3.0.7) .....	15
4.4	Determination of the layer properties .....	15
4.5	Rules of the layer concept .....	26
<b>5</b>	<b>Data concept .....</b>	<b>27</b>
5.1	Origin points and mating points .....	27
5.1.1	Rotationally symmetric cutting tool assembly .....	27
5.1.2	Non-rotationally symmetric cutting tool assembly .....	28
5.2	Rules for the Layer CUT and NOCUT .....	30
5.3	Rules for the concept of dimensioning .....	32
5.3.1	General .....	32
5.3.2	Cutting tool component .....	32
5.3.3	Cutting tool combination .....	33
<b>Annex A (informative)</b>	<b>Examples of the layer structure .....</b>	<b>34</b>
<b>Bibliography .....</b>		<b>49</b>