

DIN EN 15859:2010-08 (E)

Air Quality - Certification of automated dust arrestment plant monitors for use on stationary sources - Performance criteria and test procedures

Contents		Page
Foreword		4
0	Introduction	5
1	Scope	7
2	Normative references	7
3	Terms and definitions	7
4	Symbols and abbreviations	12
4.1	Symbols	12
4.2	Abbreviations	13
5	General requirements	14
5.1	Application of performance criteria	14
5.2	Ranges to be tested	14
5.2.1	General	14
5.2.2	Certification range for filter dust monitor	14
5.2.3	Supplementary ranges for filter dust monitors	14
5.2.4	Type of arrestment plant for filter leakage monitors	14
5.2.5	Expression of performance criteria with respect to ranges	15
5.2.6	Ranges of optical in-situ instrument with variable optical length (cross-stack)	15
5.3	Manufacturing consistency and changes to instrument design	15
5.4	Qualifications of test laboratories	15
6	Performance characteristics for laboratory testing	15
6.1	Instrument for testing	15
6.2	CE labelling	15
6.3	Security	16
6.4	Output ranges and zero-point	16
6.5	Additional outputs on filter leakage monitors	16
6.6	Display of operational status signals	16
6.7	Degrees of protection provided by enclosures	16
6.8	Response time	16
6.9	Detection time	16
6.10	Repeatability standard deviation at automatic internal zero point	16
6.11	Repeatability standard deviation at automatic internal reference point	17
6.12	Automatic internal zero and reference point checks	17
6.13	Influence of ambient temperature	17
6.14	Influence of sample gas flow for extractive instrument	17
6.15	Influence of voltage variations	17
6.16	Influence of vibration	17
6.17	Cross-sensitivity	17
6.18	Excursion of measurement beam of cross-stack in situ instruments	18
6.19	Detection limit	18
7	Performance characteristics for field testing	18
7.1	Calibration function for filter dust monitors	18
7.2	Functional test of filter leakage monitor	18
7.2.1	General	18

7.2.2	Plant failure detection test	18
7.2.3	Simulated filter failure test	19
7.3	Maintenance interval	19
7.4	Drift of automatic internal zero point and automatic internal reference point	19
7.5	Availability	19
7.6	Reproducibility	19
8	Performance criteria	19
9	General test requirements	21
10	Test procedures for laboratory tests	22
10.1	Instrument for testing	22
10.2	CE labelling	22
10.3	Security	22
10.4	Output ranges and zero point	23
10.5	Additional outputs on filter leakage monitors	23
10.6	Display of operational status signals	23
10.7	Degrees of protection provided by enclosures	23
10.8	Response time	23
10.9	Detection time	25
10.10	Repeatability standard deviation at automatic internal zero and reference points	25
10.11	Influence of ambient temperature	25
10.12	Influence of sample gas flow for extractive instruments	26
10.13	Influence of voltage variations	27
10.14	Influence of vibration	28
10.15	Cross-sensitivity	29
10.16	Excursion of measurement beam of cross-stack in situ instruments	29
10.17	Detection limit	29
11	Requirements for field tests	30
11.1	Provisions	30
11.2	Field test duration	30
12	Test procedures for field tests	30
12.1	Calibration function for filter dust monitor	30
12.2	Functional test of filter leakage monitor	31
12.2.1	Plant failure detection test	31
12.2.2	Simulated filter failure test	31
12.3	Maintenance interval	31
12.4	Drift of automatic internal zero point and automatic internal reference point	32
12.5	Availability	32
12.6	Reproducibility	33
13	Test report	35
	Annex A (informative) Elements of recommended performance testing report	36
	Bibliography	38