

# DIN EN 16909:2017-06 (E)

## Ambient air - Measurement of elemental carbon (EC) and organic carbon (OC) collected on filters

---

<b>Contents</b>		<b>Page</b>
European foreword .....		5
Introduction .....		6
1	Scope .....	7
2	Normative references .....	7
3	Terms, definitions and abbreviations .....	7
3.1	Terms and definitions .....	7
3.2	Abbreviations and acronyms .....	8
4	Principle .....	9
5	Materials and instruments .....	9
5.1	Materials .....	9
5.1.1	Gases .....	9
5.1.2	Standard solution .....	9
5.1.3	Other materials .....	9
5.2	Instruments .....	9
5.2.1	Sampling instruments .....	9
5.2.2	Analytical instruments .....	9
6	Sampling .....	10
6.1	Filter material .....	10
6.2	Preheating of filter material and handling .....	10
6.3	Sampling duration and frequency .....	10
6.4	Field sampling and type of sampler .....	11
6.5	Site types .....	11
6.6	Filter environment during sampling .....	11
7	Transport and storage .....	11
7.1	Handling .....	11
7.2	Time and temperature limits .....	11
8	Analysis .....	11
8.1	General .....	11
8.2	Thermal protocol .....	12
9	Artefacts and interferences .....	13
9.1	General .....	13
9.2	Sampling .....	13
9.3	Transport and storage .....	13
9.4	Analysis .....	14
10	Quality assurance/quality control (QA/QC) .....	14
10.1	QA/QC for sampling parameters .....	14
10.2	Field blank determination .....	14
10.3	Laboratory blank determination .....	15
10.4	Calibration for TC .....	15
10.5	Long term stability and repeatability .....	15

10.6	Other-QA/QC checks .....	15
10.6.1	Use of quality control filters .....	15
10.6.2	Calibration gas injections .....	16
10.6.3	Calibration and checks on temperature sensors and optical systems .....	16
10.6.4	Stability of the laser signal .....	16
10.7	Applicable concentration range .....	16
11	Calculation of concentrations of EC and OC .....	17
12	Data recording .....	17
13	Determination of measurement uncertainty .....	18
Annex A (informative) Example of a logbook information .....		21
Annex B (informative) An example of a standard operating procedure for analysing EC and OC .....		22
B.1	General .....	22
B.2	Start-up .....	22
B.3	Cleaning the system .....	23
B.4	Running the instrument blank .....	23
B.5	Running an external calibration standard .....	23
B.6	Running an external long term calibration standard .....	24
B.7	Running a EC/OC control sample and routine samples .....	26
B.8	Shutdown of instrument .....	26
Annex C (informative) Methods for the assessment of carbonate carbon .....		28
Annex D (informative) Preparation of stock sucrose solutions and calibration standards .....		30
Annex E (informative) Example for the determination of measurement uncertainty .....		31
Annex F (informative) Statistical analysis of Organic Carbon (OC), Elemental Carbon (EC) and Total Carbon (TC) concentrations collected on filters from field validation exercise .....		34
F.1	General .....	34
F.2	Analysis methodology .....	34
F.2.1	General .....	34
F.2.2	Calculating between- and within-laboratory variability .....	35
F.2.2.1	Notation .....	35
F.2.2.2	Data processing .....	35
F.2.2.3	Outlier rejection .....	35
F.2.2.4	Data normalization .....	36
F.2.2.5	Analysis of variance .....	37
F.2.2.6	Calculation of standard deviations .....	37
F.2.3	Calculating between-sampler variability .....	38
F.2.3.1	Notation .....	38
F.2.3.2	Data processing .....	38
F.2.4	Combined standard uncertainty .....	39
F.3	Remarks .....	39
F.4	Results .....	39
F.4.1	Data set 1 - Between laboratory and internal laboratory variability .....	39
F.4.2	Data set 2 - Between sampler variability .....	41
F.4.3	Data set 3a - Site specific ranking .....	42
F.4.4	Data set 3B - Uncertainty over the measured concentration range .....	47
Annex G (informative) Good example for an instrument blank laser signal for EUSAAR2 .....		54
Figure G.1 -- Good example for an instrument blank laser signal for EUSAAR2 including $\pm 3\%$ uncertainty limits .....		54
Bibliography .....		55