

ISO 10312:2019-10 (E)

Ambient air - Determination of asbestos fibres - Direct transfer transmission electron microscop y method

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	5
5	Type of sample	6
6	Range	6
7	Limit of detection	6
8	Principle	7
9	Reagents	7
10	Apparatus	8
10.1	Air sampling -- Equipment and consumable supplies	8
10.1.1	Filter cassette	8
10.1.2	Sampling pump	8
10.1.3	Stand	8
10.1.4	Personal sampling	8
10.1.5	Flowmeter	8
10.2	Specimen preparation laboratory	9
10.3	Equipment for analysis	9
10.3.1	Transmission electron microscope	9
10.3.2	Energy dispersive X-ray analyser	11
10.3.3	Plasma asher	11
10.3.4	Vacuum coating unit	11
10.3.5	Sputter coater	11
10.3.6	Solvent washer (Jaffe washer)	11
10.3.7	Condensation washer	12
10.3.8	Slide warmer or oven	13
10.3.9	Ultrasonic bath	13
10.3.10	Carbon grating replica	13
10.3.11	Calibration specimen grids for EDXA	13
10.3.12	Carbon rod sharpener	14
10.3.13	Disposable tip micropipettes	14
10.4	Consumable supplies	14
10.4.1	Copper or nickel electron microscope grids	14
10.4.2	Gold or nickel electron microscope grids	14
10.4.3	Carbon rod electrodes	14
10.4.4	Routine electron microscopy tools and supplies	14
10.4.5	Reference asbestos samples	14
10.4.6	Reference samples of mineral fibres other than asbestos	15

11	Air sample collection	15
12	Procedure for analysis	16
12.1	General	16
12.2	Cleaning of sample cassettes	16
12.3	Direct preparation of TEM specimens from polycarbonate filters	17
12.3.1	Selection of filter area for carbon coating	17
12.3.2	Carbon coating of filter portions	17
12.3.3	Preparation of the Jaffe washer	17
12.3.4	Placing of specimens in the Jaffe washer	17
12.4	Direct preparation of TEM specimens from cellulose ester filters	18
12.4.1	Selection of area of filter for preparation	18
12.4.2	Preparation of solution for collapsing cellulose ester filters	18
12.4.3	Filter collapsing procedure	18
12.4.4	Plasma etching of the filter surfaces	18
12.4.5	Carbon coating	18
12.4.6	Preparation of the Jaffe washer	18
12.4.7	Placing of specimens in the Jaffe washer	18
12.5	Criteria for acceptable TEM specimen grids	19
12.6	Procedure for structure counting by TEM	19
12.6.1	General	19
12.6.2	Measurement of mean opening area	20
12.6.3	TEM alignment and calibration procedures	20
12.6.4	Determination of criterion for termination of TEM examination	20
12.6.5	General procedure for structure counting and size analysis	21
12.6.6	Magnification requirements	23
12.7	Blank and quality control determinations	24
12.8	Calculation of results	24
13	Performance characteristics	25
13.1	General	25
13.2	Interferences and limitations of fibre identification	25
13.3	Precision and accuracy	25
13.3.1	Precision	25
13.3.2	Accuracy	26
13.3.3	Inter-laboratory and intra-laboratory analyses	26
13.4	Limit of detection	26
14	Test report	27
	Annex A (normative) Determination of operating conditions for plasma asher	30
	Annex B (normative) Calibration procedures	31
	Annex C (normative) Structure counting criteria	34
	Annex D (normative) Fibre identification procedure	44
	Annex E (normative) Determination of the concentration of asbestos fibres and bundles longer than 5 µm, and PCM equivalent asbestos fibres	61
	Annex F (normative) Calculation of results	62
	Annex G (informative) Strategies for collection of air samples	68
	Annex H (informative) Methods for removal of gypsum fibres	69
	Bibliography	70