

ISO 20181:2023-02 (E)

Stationary source emissions - Quality assurance of automated measuring systems

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	6
4.1	Symbols	6
4.2	Abbreviated terms	7
5	Principle	7
5.1	General	7
5.2	Limitations	9
5.3	Measurement site and installation	9
5.4	Testing laboratories performing SRM measurements	10
6	Calibration and validation of the AMS (QAL2)	10
6.1	General	10
6.2	Functional test	11
6.3	Parallel measurements with the SRM	12
6.4	Data evaluation	14
6.4.1	Preparation of data	14
6.4.2	Selection of data points from automated SRM	15
6.4.3	Establishing the calibration function	15
6.5	Calibration function of the AMS and its validity	16
6.6	Calculation of variability	18
6.7	Test of variability	19
6.8	QAL2 report	19
7	Ongoing quality assurance during operation (QAL3)	20
7.1	General	20
7.2	Procedures to maintain ongoing quality	21
7.3	Choosing control charts	21
7.4	Control chart limits	22
7.4.1	General	22
7.4.2	Calculation of control chart limits using performance data	22
7.4.3	Calculation of control chart limits using the maximum permissible uncertainty	23
7.5	Zero and span measurements	23
7.5.1	General	23
7.5.2	Frequency of zero and span measurements	23
7.5.3	Extractive gas analysis systems	24
7.5.4	In-situ gas-monitoring AMS	24
7.5.5	Particulate-monitoring AMS	25
7.6	Documentation of control charts	25
8	Annual surveillance test (AST)	25
8.1	General	25
8.2	Functional test	26

8.3	Parallel measurements with the SRM	26
8.4	Data evaluation	27
8.5	Calculation of variability	28
8.6	Test of variability and validity of the calibration function	28
8.7	AST report	29
9	Documentation	29
Annex A (normative) QAL2 and AST functional test of AMS		30
Annex B (normative) Test of linearity		34
Annex C (informative) Control charts		36
Annex D (normative) Documentation		46
Annex E (informative) Examples of calculation of the calibration function and of the variability test		48
Annex F (informative) Example of calculation of the standard deviation s_{AMS} of the AMS at zero and span level		63
Annex G (informative) Example of using the calibration function and testing the variability and validity of the calibration function in the AST		66
Annex H (informative) Implementation of QAL1		70
Annex I (normative) k_v and $t_{0,95}$; N-1 values		71
Annex J (informative) Significant technical changes		72
Bibliography		74