

DIN EN 15267-3:2024-09 (E)

Air quality - Assessment of air quality monitoring equipment - Part 3: Performance criteria and test procedures for stationary automated measuring systems for continuous monitoring of emissions from stationary sources

Contents		Page
European foreword		5
Introduction		7
1	Scope	10
2	Normative references	10
3	Terms and definitions	10
4	Symbols and abbreviations	17
5	General requirements	20
5.1	Application of performance criteria	20
5.2	Ranges to be tested	21
5.2.1	Certification range	21
5.2.2	Supplementary ranges	21
5.2.3	Lower limit of ranges	21
5.2.4	Expression of performance criteria with respect to ranges	22
5.2.5	Ranges of optical in situ AMS with variable optical length	22
5.3	Manufacturing consistency and changes to AMS design	22
5.4	Qualifications of testing laboratories	22
6	Common performance criteria for the laboratory test	22
6.1	AMS for testing	22
6.2	Evidence of compliance of legal requirements	23
6.3	Security	23
6.4	Interfaces	23
6.4.1	General	23
6.4.2	Analogue data output	23
6.4.3	Digital communication	23
6.5	Additional data outputs	24
6.6	Operational status signals	24
6.7	Prevention or compensation for optical contamination of in situ AMS	24
6.8	Degrees of protection provided by enclosures	24
6.9	Response time	24
6.10	Repeatability standard deviation at zero point	24
6.11	Repeatability standard deviation at span point	24
6.12	Lack of fit	24
6.13	Drift at zero point and at span point	24
6.14	Influence of ambient temperature	25
6.15	Influence of supply voltage variations	25
6.16	Influence of vibration	25
6.17	Influence of sample gas pressure for in situ AMS	25
6.18	Influence of sample gas flow for extractive AMS	26
6.19	Cross-sensitivity	26
6.20	Excursion of measurement beam of cross-stack in situ AMS	26
6.21	Converter efficiency for AMS measuring NO _x	26
6.22	Converter efficiency for AMS measuring Hg	26

6.23	Response factors for AMS measuring TOC	26
7	Common performance criteria for the field test	26
7.1	Calibration function	26
7.2	Response time	27
7.3	Lack of fit	27
7.4	Maintenance interval	27
7.5	Drift at zero point and at span point	27
7.6	Availability	27
7.7	Reproducibility	27
7.8	Contamination check of in situ systems	27
8	Specific performance criteria for measured components	28
8.1	General	28
8.2	AMS measuring gaseous measured components	28
8.2.1	Performance criteria	28
8.2.2	AMS measuring TOC	30
8.2.3	AMS measuring Hg	31
8.3	AMS measuring particulate matter	31
8.4	AMS measuring gas flow	33
9	General test requirements	34
10	Test procedures for the laboratory test	35
10.1	AMS for testing	35
10.2	Evidence of compliance of legal requirements	35
10.3	Security	35
10.4	Interfaces	36
10.4.1	General	36
10.4.2	Analog data output	36
10.4.3	Digital communication	36
10.5	Additional data output	36
10.6	Operational status signals	36
10.7	Prevention or compensation for optical contamination for in situ AMS	36
10.8	Degrees of protection provided by enclosures	37
10.9	Response time	37
10.10	Repeatability standard deviation at zero point	39
10.11	Repeatability standard deviation at span point	39
10.12	Lack of fit	40
10.13	Drift at zero point and at span point	41
10.14	Influence of ambient temperature	42
10.15	Influence of supply voltage variations	43
10.16	Influence of vibration	43
10.17	Influence of sample gas pressure for in situ AMS	44
10.18	Influence of sample gas flow for extractive AMS	45
10.19	Cross-sensitivity	45
10.20	Excursion of measurement beam of cross-stack in situ AMS	46
10.21	Converter efficiency for AMS measuring NOX	47
10.22	Converter efficiency for AMS measuring Hg	48
10.23	Response factors for AMS measuring TOC	48
11	Requirements for the field test	49
11.1	Provisions	49
11.2	Field test duration	49
12	Common test procedures for the field test	50
12.1	Calibration function	50
12.2	Response time	50
12.3	Lack of fit	50
12.4	Maintenance interval	51
12.5	Drift at zero point and at span point	51
12.6	Availability	52

12.7	Reproducibility	52
12.8	Contamination check of in situ systems	54
13	Specific test procedures for AMS measuring particulate matter	55
13.1	Lack of fit	55
13.2	Extractive AMS	55
14	Measurement uncertainty	55
15	Test report	56
Annex A (informative) Selected standard reference methods, reference methods and general documents		57
Annex B (normative) Interferents		59
Annex C (normative) Test of linearity		60
C.1	Description of the test procedure	60
C.2	Establishment of the regression line	60
C.3	Calculation of the residuals of the average concentrations	61
Annex D (informative) Example for the determination of the expanded uncertainty		62
D.1	Determination of uncertainty contributions	62
D.2	Elements required for the uncertainty determinations	62
D.3	Example of an uncertainty calculation for an AMS measuring SO ₂	64
D.4	Determination of uncertainty contributions by use of sensitivity coefficients	66
D.5	Example of a calculation of an uncertainty contribution by use of a sensitivity coefficient	66
Annex E (informative) Elements of a performance test report		67
Bibliography		70