

# DIN EN 15267-3:2024-09 (E)

## Air quality - Assessment of air quality monitoring equipment - Part 3: Performance criteria and test procedures for stationary automated measuring systems for continuous monitoring of emissions from stationary sources

---

<b>Contents</b>		<b>Page</b>
European foreword .....		5
Introduction .....		7
1	Scope .....	10
2	Normative references .....	10
3	Terms and definitions .....	10
4	Symbols and abbreviations .....	17
5	General requirements .....	20
5.1	Application of performance criteria .....	20
5.2	Ranges to be tested .....	21
5.2.1	Certification range .....	21
5.2.2	Supplementary ranges .....	21
5.2.3	Lower limit of ranges .....	21
5.2.4	Expression of performance criteria with respect to ranges .....	22
5.2.5	Ranges of optical in situ AMS with variable optical length .....	22
5.3	Manufacturing consistency and changes to AMS design .....	22
5.4	Qualifications of testing laboratories .....	22
6	Common performance criteria for the laboratory test .....	22
6.1	AMS for testing .....	22
6.2	Evidence of compliance of legal requirements .....	23
6.3	Security .....	23
6.4	Interfaces .....	23
6.4.1	General .....	23
6.4.2	Analogue data output .....	23
6.4.3	Digital communication .....	23
6.5	Additional data outputs .....	24
6.6	Operational status signals .....	24
6.7	Prevention or compensation for optical contamination of in situ AMS .....	24
6.8	Degrees of protection provided by enclosures .....	24
6.9	Response time .....	24
6.10	Repeatability standard deviation at zero point .....	24
6.11	Repeatability standard deviation at span point .....	24
6.12	Lack of fit .....	24
6.13	Drift at zero point and at span point .....	24
6.14	Influence of ambient temperature .....	25
6.15	Influence of supply voltage variations .....	25
6.16	Influence of vibration .....	25
6.17	Influence of sample gas pressure for in situ AMS .....	25
6.18	Influence of sample gas flow for extractive AMS .....	26
6.19	Cross-sensitivity .....	26
6.20	Excursion of measurement beam of cross-stack in situ AMS .....	26
6.21	Converter efficiency for AMS measuring NO <sub>x</sub> .....	26
6.22	Converter efficiency for AMS measuring Hg .....	26

6.23	Response factors for AMS measuring TOC .....	26
7	Common performance criteria for the field test .....	26
7.1	Calibration function .....	26
7.2	Response time .....	27
7.3	Lack of fit .....	27
7.4	Maintenance interval .....	27
7.5	Drift at zero point and at span point .....	27
7.6	Availability .....	27
7.7	Reproducibility .....	27
7.8	Contamination check of in situ systems .....	27
8	Specific performance criteria for measured components .....	28
8.1	General .....	28
8.2	AMS measuring gaseous measured components .....	28
8.2.1	Performance criteria .....	28
8.2.2	AMS measuring TOC .....	30
8.2.3	AMS measuring Hg .....	31
8.3	AMS measuring particulate matter .....	31
8.4	AMS measuring gas flow .....	33
9	General test requirements .....	34
10	Test procedures for the laboratory test .....	35
10.1	AMS for testing .....	35
10.2	Evidence of compliance of legal requirements .....	35
10.3	Security .....	35
10.4	Interfaces .....	36
10.4.1	General .....	36
10.4.2	Analog data output .....	36
10.4.3	Digital communication .....	36
10.5	Additional data output .....	36
10.6	Operational status signals .....	36
10.7	Prevention or compensation for optical contamination for in situ AMS .....	36
10.8	Degrees of protection provided by enclosures .....	37
10.9	Response time .....	37
10.10	Repeatability standard deviation at zero point .....	39
10.11	Repeatability standard deviation at span point .....	39
10.12	Lack of fit .....	40
10.13	Drift at zero point and at span point .....	41
10.14	Influence of ambient temperature .....	42
10.15	Influence of supply voltage variations .....	43
10.16	Influence of vibration .....	43
10.17	Influence of sample gas pressure for in situ AMS .....	44
10.18	Influence of sample gas flow for extractive AMS .....	45
10.19	Cross-sensitivity .....	45
10.20	Excursion of measurement beam of cross-stack in situ AMS .....	46
10.21	Converter efficiency for AMS measuring NOX .....	47
10.22	Converter efficiency for AMS measuring Hg .....	48
10.23	Response factors for AMS measuring TOC .....	48
11	Requirements for the field test .....	49
11.1	Provisions .....	49
11.2	Field test duration .....	49
12	Common test procedures for the field test .....	50
12.1	Calibration function .....	50
12.2	Response time .....	50
12.3	Lack of fit .....	50
12.4	Maintenance interval .....	51
12.5	Drift at zero point and at span point .....	51
12.6	Availability .....	52

12.7	Reproducibility .....	52
12.8	Contamination check of in situ systems .....	54
13	Specific test procedures for AMS measuring particulate matter .....	55
13.1	Lack of fit .....	55
13.2	Extractive AMS .....	55
14	Measurement uncertainty .....	55
15	Test report .....	56
Annex A (informative) Selected standard reference methods, reference methods and general documents .....		57
Annex B (normative) Interferents .....		59
Annex C (normative) Test of linearity .....		60
C.1	Description of the test procedure .....	60
C.2	Establishment of the regression line .....	60
C.3	Calculation of the residuals of the average concentrations .....	61
Annex D (informative) Example for the determination of the expanded uncertainty .....		62
D.1	Determination of uncertainty contributions .....	62
D.2	Elements required for the uncertainty determinations .....	62
D.3	Example of an uncertainty calculation for an AMS measuring SO <sub>2</sub> .....	64
D.4	Determination of uncertainty contributions by use of sensitivity coefficients .....	66
D.5	Example of a calculation of an uncertainty contribution by use of a sensitivity coefficient .....	66
Annex E (informative) Elements of a performance test report .....		67
Bibliography .....		70