

# ISO 11338-2:2003-06 (E)

## Stationary source emissions - Determination of gas and particle-phase polycyclic aromatic hydrocarbons - Part 2: Sample preparation, clean-up and determination

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	2
4.1	Sampling .....	2
4.2	Analysis .....	2
5	Safety measures .....	2
6	Procedures .....	2
6.1	HPLC method .....	2
6.2	GC-MS method .....	9
7	Limitations and interferences .....	16
7.1	Limitations .....	16
7.2	Interferences .....	17
Annex A (informative)	Maximum UV absorption wavelength and recommended combinations of excitation-emission wavelengths for HPLC .....	18
Annex B (informative)	Formulae and physical properties of selected PAH .....	19
Annex C (informative)	Characteristic ions for GC-MS detection of selected PAH, recovery, and surrogate recovery standards .....	20
Annex D (informative)	Applicability of internal standards for GC-MS detection of selected PAH .....	21
Annex E (normative)	Summary of performance characteristics of the HPLC method .....	22
Bibliography .....		23