

# DIN EN 1948-1:2006-06 (E)

## Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-like PCBs - Part 1: Sampling of PCDDs/PCDFs

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		7
1 <b>Scope</b> .....		8
2 <b>Normative references</b> .....		8
3 <b>Terms and definitions</b> .....		9
4 <b>Symbols and abbreviations</b> .....		11
5 <b>Principle of the complete PCDD/PCDF measurement procedure</b> .....		12
6 <b>Sampling device and materials</b> .....		15
7 <b>Minimum requirements for sampling</b> .....		18
8 <b>Safety measures and transport</b> .....		21
9 <b>Preparations and sampling</b> .....		21
<b>Annex A (informative) Toxicity and toxic equivalency</b> .....		27
<b>Annex B (informative) Examples of operation</b> .....		30
<b>Annex C (informative) Examples of adsorbents and their preparations and cleaning</b> .....		58
<b>Annex D (informative) Sampling measurement record</b> .....		59
<b>Annex E (informative) Relations to EU Directives</b> .....		62
<b>Bibliography</b> .....		63