

# DIN EN 1948-2:2006-06 (E)

## Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-like PCBs - Part 2: Extraction and clean-up of PCDDs/PCDFs

---

<b>Contents</b>		<b>Page</b>
	Foreword .....	3
	Introduction .....	6
1	Scope .....	7
2	Normative references .....	7
3	Terms and definitions .....	7
4	Symbols and abbreviations .....	10
5	Principle of the extraction and clean-up procedure .....	11
6	Device, materials and 13 C12-labelled standards .....	12
7	Method validation and quality control requirements .....	13
8	Sample pre-treatment and extraction .....	14
9	Report .....	16
	Annex A (informative) Examples of operation of extraction and clean-up methods .....	17
	Annex B (informative) Relations to EU Directives .....	35
	Bibliography .....	36