

DIN EN ISO 4619:2011-02 (E)

Driers for paints and varnishes (ISO 4619:1998)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Definition	5
4	Descriptions	5
4.1	Solid driers	5
4.2	Liquid driers	5
4.3	Metals used	5
4.4	Acids used	5
5	Requirements and test methods	5
6	Sampling	5
7	Methods of test for solid driers	6
7.1	Appearance and consistency	6
7.2	Colour	6
7.3	Solubility (miscibility) in solvents, raw linseed oil or other drying media	7
7.4	Stability of solution	7
7.5	Suspended solid matter	7
7.6	Volatile matter	7
7.7	Acidity or basicity	7
8	Methods of test for liquid driers	10
8.1	Appearance	10
8.2	Colour	10
8.3	Solubility (miscibility) in solvents, raw linseed oil or other drying media	10
8.4	Stability of solution	10
8.5	Viscosity	11
9	Methods for determination of metal content of driers containing only one metal	11
9.1	Cobalt (EDTA titrimetric method)	11
9.2	Manganese (EDTA titrimetric method)	12
9.3	Lead (EDTA titrimetric method)	13
9.4	Zinc (EDTA titrimetric method)	14
9.5	Calcium (EDTA titrimetric method)	15
9.6	Iron (iodometric method)	16
9.7	Zirconium (EDTA titrimetric method)	17
9.8	Barium	18
10	Methods for determination of metal contents of mixed driers	20
11	Test report	20