

DIN EN ISO 2811-1:2011-06 (E)

Paints and varnishes - Determination of density - Part 1: Pyknometer method (ISO 2811-1:2011)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	4
4	Principle	4
5	Temperature	5
6	Apparatus	5
7	Sampling	5
8	Procedure	5
8.1	General	5
8.2	Determination	6
9	Calculation	7
10	Precision	7
10.1	Repeatability limit, r	7
10.2	Reproducibility limit, R	7
11	Test report	8
Annex A (informative) Example of a calibration method		9
Annex B (informative) Temperature variation		11
Bibliography		13