

# ISO 16474-2:2013-11 (E)

## Paints and varnishes - Methods of exposure to laboratory light sources - Part 2: Xenon-arc lamps

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	2
5	Apparatus .....	3
5.1	Laboratory light source .....	3
5.2	Test chamber .....	4
5.3	Radiometer .....	5
5.4	Black-standard/black-panel thermometer .....	5
5.5	Wetting and humidity-control equipment .....	5
5.6	Specimen holders .....	5
5.7	Apparatus to assess changes in properties .....	6
6	Test specimens .....	6
7	Exposure conditions .....	6
7.1	Radiation .....	6
7.2	Temperature .....	6
7.3	Relative humidity of chamber air .....	7
7.4	Spray cycle .....	8
7.5	Cycles with dark periods .....	8
7.6	Sets of exposure conditions .....	9
8	Procedure .....	9
8.1	General .....	9
8.2	Mounting the test specimens .....	9
8.3	Exposure .....	9
8.4	Duration of test .....	10
8.5	Measurement of radiant exposure .....	10
8.6	Determination of changes in properties after exposure .....	10
9	Test report .....	10
Annex A (informative) Filtered xenon-arc radiation -- Spectral power distribution .....		11
Annex B (normative) Additional exposure cycles .....		13
Bibliography .....		15