

ISO 16474-2:2013-11 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 2: Xenon-arc lamps

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Apparatus	3
5.1	Laboratory light source	3
5.2	Test chamber	4
5.3	Radiometer	5
5.4	Black-standard/black-panel thermometer	5
5.5	Wetting and humidity-control equipment	5
5.6	Specimen holders	5
5.7	Apparatus to assess changes in properties	6
6	Test specimens	6
7	Exposure conditions	6
7.1	Radiation	6
7.2	Temperature	6
7.3	Relative humidity of chamber air	7
7.4	Spray cycle	8
7.5	Cycles with dark periods	8
7.6	Sets of exposure conditions	9
8	Procedure	9
8.1	General	9
8.2	Mounting the test specimens	9
8.3	Exposure	9
8.4	Duration of test	10
8.5	Measurement of radiant exposure	10
8.6	Determination of changes in properties after exposure	10
9	Test report	10
Annex A (informative) Filtered xenon-arc radiation -- Spectral power distribution		11
Annex B (normative) Additional exposure cycles		13
Bibliography		15