

ISO 16474-4:2013-11 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 4: Open-flame carbon-arc lamps

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Apparatus	2
5.1	Laboratory light source	2
5.2	Test chamber	6
5.3	Radiometer	6
5.4	Black-standard/black-panel thermometer	6
5.5	Wetting and humidity-control equipment	6
5.6	Specimen holders	7
5.7	Apparatus to assess changes in properties	7
6	Test specimens	7
7	Exposure conditions	7
7.1	Temperature	7
7.2	Relative humidity of chamber air	8
7.3	Spray cycle	8
8	Procedure	8
8.1	General	8
8.2	Mounting the test specimens	8
8.3	Exposure	8
8.4	Duration of test	9
8.5	Measurement of radiant exposure	9
8.6	Determination of changes in properties after exposure	9
9	Test report	9
Bibliography		10