

# ISO 8130-1:2019 (E)

## Coating powders — Part 1: Determination of particle size distribution by sieving

---

### Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Principle
5	Apparatus
6	Sampling
7	Choice of sieving method and sieve selectivity
8	Preparation of the test sieve
9	Procedure
9.1	Number of determinations
9.2	Manual sieving (with mesh sizes greater than 100 µm)
9.3	Machine sieving using an air-jet sieve apparatus
9.4	Machine sieving using vibration mechanism
10	Expression of results
11	Precision
12	Test report
Annex A	(informative) Nominal sizes of test sieves

Page count: 9