

ISO 4628-1:2003-09 (E)

Paints and varnishes - Evaluation of degradation of coatings; Designation of quantity and size of defects, and of intensity of uniform changes in appearance - Part 1: General introduction and designation system

Contents		Page
Foreword		iv
1	Scope	1
2	General principles of the designation system	1
3	Assessment of defects and of intensity of changes	1
3.1	General	1
3.2	Designation of quantity of defects	2
3.3	Designation of size of defects	2
3.4	Designation of intensity of changes	2
4	Expression of results	3
5	Test report	3