

ISO 8502-6:2006-07 (E)

Preparation of steel substrates before application of paints and related products -
Tests for the assessment of surface cleanliness - Part 6: Extraction of soluble
contaminants for analysis - The Bresle method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Principle	1
4	Apparatus and materials	2
5	Procedure	2
6	Test report	3
Annex A (normative) Leak test for type testing of patches		6