

# ISO 2808:2007-02 (E)

## Paints and varnishes - Determination of film thickness

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Determination of wet-film thickness .....</b>	<b>3</b>
4.1	General .....	3
4.2	Mechanical methods .....	3
4.2.1	Principle .....	3
4.2.2	Field of application .....	3
4.2.3	General .....	3
4.2.4	Method 1A -- Comb gauge .....	4
4.2.5	Method 1B -- Wheel gauge .....	5
4.2.6	Method 1C -- Dial gauge .....	6
4.3	Gravimetric method .....	7
4.3.1	Principle .....	7
4.3.2	Field of application .....	7
4.3.3	General .....	7
4.3.4	Method 2 -- By difference in mass .....	7
4.4	Photothermal method .....	8
4.4.1	Principle .....	8
4.4.2	Field of application .....	8
4.4.3	General .....	9
4.4.4	Method 3 -- Determination using thermal properties .....	9
<b>5</b>	<b>Determination of dry-film thickness .....</b>	<b>9</b>
5.1	General .....	9
5.2	Mechanical methods .....	9
5.2.1	Principle .....	9
5.2.2	Field of application .....	10
5.2.3	General .....	10
5.2.4	Method 4A -- By difference in thickness .....	11
5.2.5	Method 4B -- Depth gauging .....	13
5.2.6	Method 4C -- Surface profile scanning .....	15
5.3	Gravimetric method .....	16
5.3.1	Principle .....	16
5.3.2	Field of application .....	16
5.3.3	General .....	16
5.3.4	Method 5 -- By difference in mass .....	16
5.4	Optical methods .....	17
5.4.1	Principle .....	17
5.4.2	Field of application .....	18
5.4.3	General .....	18
5.4.4	Method 6A -- Cross-sectioning .....	19
5.4.5	Method 6B -- Wedge cut .....	20
5.5	Magnetic methods .....	20
5.5.1	General .....	20

5.5.2	Principle .....	20
5.5.3	Field of application .....	20
5.5.4	General .....	21
5.5.5	Method 7A -- Magnetic pull-off gauge .....	21
5.5.6	Method 7B -- Magnetic-flux gauge .....	22
5.5.7	Method 7C -- Magnetic-induction gauge .....	22
5.5.8	Method 7D -- Eddy-current gauge .....	23
5.6	Radiological method .....	24
5.6.1	Principle .....	24
5.6.2	Field of application .....	24
5.6.3	General .....	24
5.6.4	Method 8 -- Beta backscatter method .....	25
5.7	Photothermal method .....	25
5.7.1	Principle .....	25
5.7.2	Field of application .....	26
5.7.3	General .....	26
5.7.4	Method 9 -- Determination using thermal properties .....	27
5.8	Acoustic method .....	27
5.8.1	Principle .....	27
5.8.2	Field of application .....	27
5.8.3	General .....	27
5.8.4	Method 10 -- Ultrasonic thickness gauge .....	28
6	Determination of thickness of uncured powder layers .....	28
6.1	General .....	28
6.2	Gravimetric method .....	29
6.2.1	Principle .....	29
6.2.2	Field of application .....	29
6.2.3	General .....	29
6.2.4	Method 11 -- By difference in mass .....	29
6.3	Magnetic methods .....	29
6.3.1	Principle .....	29
6.3.2	Field of application .....	29
6.3.3	General .....	30
6.3.4	Method 12A -- Magnetic-induction gauge .....	30
6.3.5	Method 12B -- Eddy-current gauge .....	31
6.4	Photothermal method .....	31
6.4.1	Principle .....	31
6.4.2	Field of application .....	31
6.4.3	General .....	31
6.4.4	Method 13 -- Determination using thermal properties .....	31
7	Measurement of film thickness on rough surfaces .....	32
7.1	General .....	32
7.2	Apparatus and materials .....	33
7.3	Procedure .....	33
7.3.1	Verification .....	33
7.3.2	Measurement .....	33
7.3.3	Number of readings .....	33
8	Test report .....	33
	Annex A (informative) Overview of methods .....	35
	Bibliography .....	38