

ISO 5660-1:2015-03 (E)

Reaction-to-fire tests - Heat release, smoke production and mass loss rate - Part 1: Heat release rate (cone calorimeter method) and smoke production rate (dynamic measurement)

Contents		Page
Foreword		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	3
5	Principle	4
6	Apparatus	5
6.1	General	5
6.2	Cone-shaped radiant electrical heater	5
6.3	Radiation shield	5
6.4	Irradiance control	5
6.5	Weighing device	5
6.6	Specimen holder	6
6.7	Retainer frame	6
6.8	Exhaust gas system with flow measuring instrumentation	6
6.9	Gas sampling apparatus	6
6.10	Ignition circuit	7
6.11	Ignition timer	7
6.12	Oxygen analyser	7
6.13	Heat flux meters	7
6.14	Calibration burner	7
6.15	Data collection and analysis system	8
6.16	Optional side screens	8
6.17	Smoke obscuration measuring system	8
6.18	Smoke system thermocouple	8
6.19	Optical filters	8
7	Suitability of a product for testing	9
7.1	Surface characteristics	9
7.2	Asymmetrical products	9
7.3	Materials of short burning time	9
7.4	Composite specimens	9
7.5	Dimensionally unstable materials	9
7.6	Materials that require testing under compression	10
8	Specimen construction and preparation	10
8.1	Specimens	10
8.2	Conditioning of specimens	10
8.3	Preparation	11
8.3.1	Specimen wrapping	11
8.3.2	Specimen preparation	11
8.3.3	Preparing specimens of materials that require testing under compression	11

9	Test environment	11
10	Calibration	12
10.1	Preliminary calibrations	12
10.1.1	General	12
10.1.2	Irradiance control system response characteristics	12
10.1.3	Weighing device response time	12
10.1.4	Weighing device output drift	12
10.1.5	Oxygen analyser delay and response times	12
10.1.6	Oxygen analyser output noise and drift	13
10.1.7	Effect of side screens	13
10.2	Operating calibrations	14
10.2.1	General	14
10.2.2	Weighing device accuracy	14
10.2.3	Oxygen analyser	14
10.2.4	Heat release rate calibration	14
10.2.5	Heater calibration	15
10.3	Smoke meter calibration	15
10.3.1	Calibration with neutral density filters	15
10.3.2	Calibration before test	15
10.4	Less frequent calibrations	15
10.4.1	Operating heat flux meter calibration	15
10.4.2	Linearity of heat release rate measurements	15
10.4.3	Accuracy of calibration burner flow meter	15
11	Test procedure	16
11.1	General precautions	16
11.2	Initial preparation	16
11.3	Procedure	16
12	Calculations	17
12.1	General	17
12.2	Calibration constant for oxygen consumption analysis	18
12.3	Heat release rate	18
12.4	Exhaust duct flow rate	18
12.5	Mass loss rate	19
12.6	Smoke obscuration	19
13	Test report	20
	Annex A (informative) Commentary and guidance notes for operators	31
	Annex B (informative) Supplementary calculations -- Normalization to the mass loss rate of the specific extinction area of specimen	36
	Annex C (informative) Resolution, precision and bias	38
	Annex D (informative) Mass loss rate and effective heat of combustion	44
	Annex E (informative) Testing in the vertical orientation	45
	Annex F (informative) Calibration of the working heat flux meter	48
	Annex G (informative) Calculation of heat release with additional gas analysis	49
	Annex H (informative) Calculation of Effective Critical Heat Flux for Ignition	53
	Bibliography	54