

DIN 66165-1:2016-08 (E)

Particle size analysis - Sieving analysis - Part 1: Fundamentals

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	4
4	Methods of test sieving	4
5	Factors affecting test sieving	5
5.1	General	5
5.2	Equipment- and process-related factors	5
5.2.1	Size and shape of sieve apertures, distribution of sieve aperture sizes	5
5.2.2	Effective sieving area	6
5.2.3	Movement of sieve or fluid	6
5.2.4	Sieving aids	6
5.2.5	Sieving using a set of test sieves	6
5.3	Material-related factors	6
5.3.1	Mass and bulk volume of the material to be sieved	6
5.3.2	Particle size distribution	7
5.3.3	Shape of particles	7
5.3.4	Tendency to agglomerate and to cohere	7
5.3.5	Susceptibility to abrasion and fracture	8
5.4	Sieving duration	8
6	Determination of cut point	9
7	Selecting the sieve aperture sizes	9
8	Analytical errors	10
9	Checking and maintenance of the test sieves	10
10	Calibration using reference material	11
10.1	Requirements to be met by the reference material	11
10.2	Calibration procedure	11
11	Determining the distribution of the sieve aperture sizes	11
Bibliography		12