

ISO 19430:2016-12 (E)

Particle size analysis - Particle tracking analysis (PTA) method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	4
5	Principles	4
5.1	General	4
5.2	Key physical parameters	5
5.3	Detection limits	5
5.3.1	Lower size limit	5
5.3.2	Upper size limit	6
5.3.3	Sample and sampling volume	6
5.3.4	Maximum particle number concentration	6
5.3.5	Minimum particle number concentration	7
5.4	Measurement precision and uncertainties	7
5.4.1	General	7
5.4.2	Measurement precision	7
5.4.3	Size range	8
5.4.4	Counting efficiency	8
5.4.5	Sizing accuracy	9
5.4.6	Size resolution	9
6	Apparatus	10
7	Procedure	11
7.1	General	11
7.2	Sample preparation	12
7.3	Instrument set-up and initialisation	12
7.4	Measurement	13
7.4.1	Sample delivery	13
7.4.2	Sample illumination	13
7.4.3	Particle imaging and tracking	14
7.4.4	Track analysis	14
7.5	Results evaluation	14
7.5.1	General	14
7.5.2	Particle size evaluation	14
7.5.3	Distribution analysis	14
7.5.4	Data analysis and reporting	14
8	System qualification and quality control	15
8.1	General	15
8.2	System installation requirements	15
8.3	System maintenance	15
8.4	System operation	15
8.5	System qualification	16

9	Data recording	17
10	Test report	17
	Annex A (informative) Theory	20
	Annex B (informative) Apparatus settings and best practice	23
	Bibliography	25