

DIN 66165-1:2022-06 (E)

Particle size analysis - Sieving analysis - Part 1: Fundamentals

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	4
4	Methods of test sieving	4
5	Factors affecting test sieving	5
5.1	General	5
5.2	Equipment- and process-related factors	6
5.2.1	Size and shape of sieve openings, distribution of sieve openings	6
5.2.2	Effective sieving area	6
5.2.3	Movement of sieve or fluid	6
5.2.4	Sieving aids	6
5.2.5	Sieving using a set of test sieves	6
5.3	Material-related factors:	6
5.3.1	Mass and bulk volume of the material to be sieved (sample)	6
5.3.2	Particle size distribution	8
5.3.3	Shape of particles	8
5.3.4	Tendency to agglomerate and to cohere	8
5.3.5	Susceptibility to abrasion and fracture	8
5.4	Sieving time	8
6	Determination of cut point	9
7	Selecting the sieve openings	10
8	Analytical errors	10
9	Checking and maintenance of the test sieves	10
10	Calibration using reference material	11
10.1	Requirements to be met by the reference material	11
10.2	Calibration procedure	12
11	Determining the distribution of the sieve opening sizes	12
Bibliography		13
Figures Figure 1 -- Plot of sieving time as a function of d_d		9
Tables Table 1 -- Methods of sieve analysis		5
Table 2 -- Maximum permissible bulk volume of the oversize as a function of opening size		7