

DIN EN 12272-3:2026-02 (E)

Surface dressing - Test methods - Part 3: Determination of binder aggregate adhesivity by the Vialit plate shock test method

Contents		Page
European foreword		4
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	7
4	Active adhesivity, mechanical adhesion and Vialit emulsion adhesivity	7
4.1	Description	7
4.2	Apparatus	8
4.2.1	Flat steel plates	8
4.2.2	3-pointed supports	8
4.2.3	Steel ball	10
4.2.4	Rubber wheel roller	10
4.2.5	Sprayer	10
4.2.6	Balance	10
4.2.7	Climatic chambers	10
4.2.8	Oven	10
4.2.9	Auxiliary items	11
4.3	Procedure	11
4.3.1	Preparation of the binder	11
4.3.2	Preparation of the chippings	11
4.3.3	Preparation of the plates	12
4.3.4	Chippings spreading	12
4.3.5	Temperatures setting	12
4.3.6	Implementation	13
4.4	Expression of results	13
4.5	Test report	14
5	Wetting temperature (only for anhydrous binders)	14
5.1	Description	14
5.2	Apparatus	14
5.3	Procedure	14
5.3.1	Preparation of the binder	14
5.3.2	Preparation of the chippings	15
5.3.3	Preparation of the plates	15
5.3.4	Chippings spreading and rolling	15
5.3.5	Temperatures setting	15
5.3.6	Implementation	15
5.4	Expression of results	15
5.5	Test report	15
6	Fragility temperature (only for anhydrous binders)	15
6.1	Description	15
6.2	Apparatus	15
6.3	Procedure	16
6.3.1	Preparation of the binder	16
6.3.2	Preparation of the chippings	16

6.3.3	Preparation of the plates	16
6.3.4	Spreading and rolling (hot bituminous binders)	16
6.3.5	Temperature setting	16
6.3.6	Implementation	16
6.4	Expression of results	16
6.5	Test report	16
7	Test report	16
Annex A (informative) Summary of the preparation of the plates before testing		18
Annex B (informative) Tables of results		21
Annex C (informative) Measures of the fragility temperature		23
Annex D (informative) Purpose of the Vialit plate shock test		24
Bibliography		25