

DIN EN ISO 13732-1:2008-12 (E)

Ergonomics of the thermal environment - Methods for the assessment of human responses to contact with surfaces - Part 1: Hot surfaces (ISO 13732-1:2006)

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	6
3	Terms and definitions	6
4	Burn thresholds	7
4.1	General	7
4.2	Burn threshold data	8
5	Assessment of risk of burning	14
5.1	Procedure	14
5.2	Identification of hot, touchable surfaces	14
5.3	Task analysis	15
5.4	Measurements of surface temperatures	15
5.5	Choice of applicable burn threshold value	16
5.6	Comparison of surface temperature and burn threshold	17
5.7	Determination of risk of burning	18
5.8	Repetition	18
6	Protective measures	19
6.1	General	19
6.2	No risk of burning	19
6.3	Risk of burning	19
7	Guidance for setting surface temperature limit values	20
7.1	Procedure	20
7.2	Assessment of risk of burning	20
7.3	Decision upon protective measures	20
7.4	Selection of appropriate values	20
7.5	Setting of surface temperature limit value	21
Annex A (informative)	Scientific background	22
Annex B (normative)	Contact periods	24
Annex C (informative)	Flow charts for application of this part of ISO 13732	25
Annex D (informative)	Thermal properties of selected materials	27
Annex E (informative)	Examples of protective measures against burns	28
Annex F (informative)	Example for assessment of risk of burning	30
Annex G (informative)	Examples for setting surface temperature limit values	35

Annex ZA (informative) Relationship between this European Standard and the Essential Annex ZB (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC	41
Requirements of EU Directive 2006/42/EC	42
Bibliography	43
Annex H (informative) Safety signs for hot surfaces	39