

DIN EN ISO 13732-1:2008-12 (E)

Ergonomics of the thermal environment - Methods for the assessment of human responses to contact with surfaces - Part 1: Hot surfaces (ISO 13732-1:2006)

Contents		Page
Foreword		3
Introduction		4
1 Scope		5
2 Normative references		6
3 Terms and definitions		6
4 Burn thresholds		7
4.1 General		7
4.2 Burn threshold data		8
5 Assessment of risk of burning		14
5.1 Procedure		14
5.2 Identification of hot, touchable surfaces		14
5.3 Task analysis		15
5.4 Measurements of surface temperatures		15
5.5 Choice of applicable burn threshold value		16
5.6 Comparison of surface temperature and burn threshold		17
5.7 Determination of risk of burning		18
5.8 Repetition		18
6 Protective measures		19
6.1 General		19
6.2 No risk of burning		19
6.3 Risk of burning		19
7 Guidance for setting surface temperature limit values		20
7.1 Procedure		20
7.2 Assessment of risk of burning		20
7.3 Decision upon protective measures		20
7.4 Selection of appropriate values		20
7.5 Setting of surface temperature limit value		21
Annex A (informative) Scientific background		22
Annex B (normative) Contact periods		24
Annex C (informative) Flow charts for application of this part of ISO 13732		25
Annex D (informative) Thermal properties of selected materials		27
Annex E (informative) Examples of protective measures against burns		28
Annex F (informative) Example for assessment of risk of burning		30
Annex G (informative) Examples for setting surface temperature limit values		35

Annex ZA (informative) Relationship between this European Standard and the Essential Annex ZB (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC	41
Requirements of EU Directive 2006/42/EC	42
Bibliography	43
Annex H (informative) Safety signs for hot surfaces	39