

# ISO 7726:1998-11 (E)

## Ergonomics of the thermal environment - Instruments for measuring physical quantities

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative reference .....</b>	<b>1</b>
<b>3</b>	<b>General .....</b>	<b>1</b>
<b>4</b>	<b>Measuring instruments .....</b>	<b>2</b>
<b>5</b>	<b>Specifications relating to measuring methods .....</b>	<b>5</b>
<b>Annex A Measurement of air temperature .....</b>		<b>12</b>
<b>Annex B Measurement of the mean radiant temperature .....</b>		<b>14</b>
<b>Annex C Measurement of plane radiant temperature .....</b>		<b>28</b>
<b>Annex D Measurement of the absolute humidity of the air .....</b>		<b>35</b>
<b>Annex E Measurement of air velocity .....</b>		<b>45</b>
<b>Annex F Measurement of surface temperature .....</b>		<b>48</b>
<b>Annex G Measurement of operative temperature .....</b>		<b>49</b>
<b>Annex H Bibliography .....</b>		<b>51</b>