

# DIN 6930-1:2011-10 (E)

## Stamped steel parts - Part 1: Technical delivery conditions

---

<b>Contents</b>		<b>Page</b>
	<b>Foreword</b> .....	<b>3</b>
<b>1</b>	<b>Scope</b> .....	<b>4</b>
<b>2</b>	<b>Normative references</b> .....	<b>4</b>
<b>3</b>	<b>Flat products</b> .....	<b>4</b>
<b>4</b>	<b>Requirements</b> .....	<b>5</b>
<b>4.1</b>	<b>General</b> .....	<b>5</b>
<b>4.2</b>	<b>General tolerances</b> .....	<b>5</b>
<b>4.3</b>	<b>Surfaces</b> .....	<b>5</b>
<b>4.4</b>	<b>Cut edges</b> .....	<b>5</b>
<b>4.5</b>	<b>Cut surfaces</b> .....	<b>6</b>
<b>4.6</b>	<b>Deviation from ordered quantities</b> .....	<b>6</b>
<b>5</b>	<b>Order information</b> .....	<b>6</b>
<b>5.1</b>	<b>General</b> .....	<b>6</b>
<b>5.2</b>	<b>Drawings</b> .....	<b>6</b>
<b>5.3</b>	<b>Material, as-delivered condition</b> .....	<b>6</b>
<b>5.4</b>	<b>Marking</b> .....	<b>7</b>
<b>6</b>	<b>Heat treatment</b> .....	<b>7</b>
<b>7</b>	<b>Tools</b> .....	<b>7</b>
<b>7.1</b>	<b>Purchaser-tied tools</b> .....	<b>7</b>
<b>7.2</b>	<b>Tools not tied to a particular purchaser</b> .....	<b>7</b>
<b>8</b>	<b>Inspection and testing</b> .....	<b>7</b>
<b>8.1</b>	<b>General</b> .....	<b>7</b>
<b>8.2</b>	<b>Normal inspection and test methods</b> .....	<b>7</b>
<b>8.3</b>	<b>Additional inspection and test methods</b> .....	<b>8</b>
<b>9</b>	<b>Certification of quality for delivery</b> .....	<b>8</b>
	<b>Bibliography</b> .....	<b>9</b>