

# DIN ISO 9211-4:2008-06 (E)

## Optics and optical instruments - Optical coatings - Part 4: Specific test methods (ISO 9211-4:2006)

---

<b>Contents</b>		<b>Page</b>
National foreword .....		3
National Annex NA (informative) Bibliography .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Test conditioning .....	5
5	Abrasion resistance tests (conditioning method 01: abrasion) .....	5
5.1	General .....	5
5.2	Test conditions .....	6
5.3	Degree of severity (conditioning method 01: abrasion) .....	6
5.4	Recovery .....	6
5.5	Evaluation .....	6
6	Adhesion tests (conditioning method 02: adhesion) .....	7
6.1	General .....	7
6.2	Test conditions .....	7
6.3	Degree of severity (conditioning method 02: adhesion) .....	7
6.4	Recovery .....	7
6.5	Evaluation .....	7
7	Crosshatch test (conditioning method 03: crosshatch) .....	8
7.1	General .....	8
7.2	Test conditions .....	8
7.3	Conditioning .....	8
7.4	Recovery .....	8
7.5	Evaluation .....	8
8	Solubility tests (conditioning method 04: solubility) .....	9
8.1	General .....	9
8.2	Test conditions .....	9
8.3	Degree of severity (conditioning method 04: solubility) .....	9
8.4	Recovery .....	10
8.5	Evaluation .....	10
9	Environmental test code .....	10
Annex A (normative) Materials for abrasion testing of optical coatings .....		11
Annex B (normative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings .....		14
Annex C (informative) Visual examination of optical coatings .....		16
Bibliography .....		17