

DIN ISO 9211-4:2008-06 (E)

Optics and optical instruments - Optical coatings - Part 4: Specific test methods (ISO 9211-4:2006)

Contents		Page
National foreword		3
National Annex NA (informative) Bibliography		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Test conditioning	5
5	Abrasion resistance tests (conditioning method 01: abrasion)	5
5.1	General	5
5.2	Test conditions	6
5.3	Degree of severity (conditioning method 01: abrasion)	6
5.4	Recovery	6
5.5	Evaluation	6
6	Adhesion tests (conditioning method 02: adhesion)	7
6.1	General	7
6.2	Test conditions	7
6.3	Degree of severity (conditioning method 02: adhesion)	7
6.4	Recovery	7
6.5	Evaluation	7
7	Crosshatch test (conditioning method 03: crosshatch)	8
7.1	General	8
7.2	Test conditions	8
7.3	Conditioning	8
7.4	Recovery	8
7.5	Evaluation	8
8	Solubility tests (conditioning method 04: solubility)	9
8.1	General	9
8.2	Test conditions	9
8.3	Degree of severity (conditioning method 04: solubility)	9
8.4	Recovery	10
8.5	Evaluation	10
9	Environmental test code	10
Annex A (normative) Materials for abrasion testing of optical coatings		11
Annex B (normative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings		14
Annex C (informative) Visual examination of optical coatings		16
Bibliography		17