

DIN ISO 9211-4:2008-06 (E)

Optics and optical instruments - Optical coatings - Part 4: Specific test methods (ISO 9211-4:2006)

Contents	Page
National foreword	3
National Annex NA (informative) Bibliography	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Test conditioning	5
5 Abrasion resistance tests (conditioning method 01: abrasion)	5
5.1 General	5
5.2 Test conditions	6
5.3 Degree of severity (conditioning method 01: abrasion)	6
5.4 Recovery	6
5.5 Evaluation	6
6 Adhesion tests (conditioning method 02: adhesion)	7
6.1 General	7
6.2 Test conditions	7
6.3 Degree of severity (conditioning method 02: adhesion)	7
6.4 Recovery	7
6.5 Evaluation	7
7 Crosshatch test (conditioning method 03: crosshatch)	8
7.1 General	8
7.2 Test conditions	8
7.3 Conditioning	8
7.4 Recovery	8
7.5 Evaluation	8
8 Solubility tests (conditioning method 04: solubility)	9
8.1 General	9
8.2 Test conditions	9
8.3 Degree of severity (conditioning method 04: solubility)	9
8.4 Recovery	10
8.5 Evaluation	10
9 Environmental test code	10
Annex A (normative) Materials for abrasion testing of optical coatings	11
Annex B (normative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings	14
Annex C (informative) Visual examination of optical coatings	16
Bibliography	17