

DIN EN 1811:2008-06 (E)

Reference test method for release of nickel from products intended to come into direct and prolonged contact with the skin (includes Amendment A1:2008)

Contents		Page
Foreword		3
Introduction		4
1 Scope		4
2 Principle		4
3 Reagents		4
4 Apparatus		6
5 Samples		6
6 Procedure		7
7 Calculations		8
8 Test report		9
significant areas		14
C.1 Identification and determination of sample area		14
C.2 Coating of non-significant areas		14
Bibliography		16
Annex C (informative) Identification and determination of sample area; and coating of non- Annex B (informative) Rules for production and preparation of reference material		12
Annex D (informative) Articles made from materials that can release small amounts of nickel		15
Annex A (informative) Statistical uncertainty of the test procedure and interpretation of results		10