

ISO 14997:2011-04 (E)

Optics and photonics - Test methods for surface imperfections of optical elements

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Physical principles		2
5 Measurement of obscured or affected area		2
5.1 General		2
5.2 Requirements		4
5.3 Calibration		4
5.4 Procedure		4
5.5 Test report		4
Annex A (informative) Component inspection		6
Annex B (informative) Recommended dimensions of artefacts on a scale comparison plate		7
Annex C (informative) Description of the instrument used for measuring imperfections below 0,01 mm: microscope image comparator		8
Annex D (informative) Imperfection quality control		11
Annex E (normative) Preferred values of grade numbers and subdivision factors		13
Bibliography		14