

# ISO 14997:2011-04 (E)

## Optics and photonics - Test methods for surface imperfections of optical elements

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b> <b>Scope</b> .....		<b>1</b>
<b>2</b> <b>Normative references</b> .....		<b>1</b>
<b>3</b> <b>Terms and definitions</b> .....		<b>1</b>
<b>4</b> <b>Physical principles</b> .....		<b>2</b>
<b>5</b> <b>Measurement of obscured or affected area</b> .....		<b>2</b>
5.1 <b>General</b> .....		<b>2</b>
5.2 <b>Requirements</b> .....		<b>4</b>
5.3 <b>Calibration</b> .....		<b>4</b>
5.4 <b>Procedure</b> .....		<b>4</b>
5.5 <b>Test report</b> .....		<b>4</b>
<b>Annex A (informative) Component inspection</b> .....		<b>6</b>
<b>Annex B (informative) Recommended dimensions of artefacts on a scale comparison plate</b> .....		<b>7</b>
<b>Annex C (informative) Description of the instrument used for measuring imperfections below 0,01 mm: microscope image comparator</b> .....		<b>8</b>
<b>Annex D (informative) Imperfection quality control</b> .....		<b>11</b>
<b>Annex E (normative) Preferred values of grade numbers and subdivision factors</b> .....		<b>13</b>
<b>Bibliography</b> .....		<b>14</b>