

ISO 9022-22:2012-04 (E)

Optics and photonics - Environmental test methods - Part 22: Combined cold, dry heat or temperature change with bump or random vibration

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	General information and test conditions	1
5	Conditioning	2
5.1	General	2
5.2	Conditioning method 22: Cold, dry heat or temperature change combined with bump or random vibration	2
6	Procedure	3
6.1	General	3
6.2	Test sequence with cold or dry heat testing	3
6.3	Test sequence with temperature change	3
6.4	Operating condition of specimen	3
6.5	Mechanical conditioning of specimen	4
7	Environmental test code	4
8	Specification	5
Annex A (informative) Explanatory notes		6
Bibliography		7