

ISO 9211-4:2012-08 (E)

Optics and photonics - Optical coatings - Part 4: Specific test methods

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Test conditioning	1
5	Abrasion resistance tests (conditioning method 01: abrasion)	1
5.1	General	1
5.2	Test conditions	2
5.3	Degree of severity (conditioning method 01: abrasion)	2
5.4	Recovery	2
5.5	Evaluation	2
6	Adhesion tests (conditioning method 02: adhesion)	3
6.1	General	3
6.2	Test conditions	3
6.3	Degree of severity (conditioning method 02: adhesion)	3
6.4	Recovery	3
6.5	Evaluation	3
7	Crosshatch test (conditioning method 03: crosshatch)	4
7.1	General	4
7.2	Test conditions	4
7.3	Conditioning	4
7.4	Recovery	4
7.5	Evaluation	4
8	Solubility tests (conditioning method 04: solubility)	5
8.1	General	5
8.2	Test conditions	5
8.3	Degree of severity (conditioning method 04: solubility)	6
8.4	Recovery	6
8.5	Evaluation	6
9	Environmental test code	7
Annex A (normative) Materials for abrasion testing of optical coatings		8
Annex B (normative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings		11
Annex C (normative) Visual examination of optical coatings		13
Bibliography		14