

ISO 9022-8:2015-03 (E)

Optics and photonics - Environmental test methods - Part 8: High internal pressure, low internal pressure, immersion

Contents		Page
Foreword	iv
Introduction	vi
1 Scope	1
2 Normative references	1
3 General information and test conditions	1
4 Conditioning	1
4.1 Conditioning method 80: High internal pressure	1
4.2 Conditioning method 81: Low internal pressure	1
4.3 Conditioning method 82: Immersion	2
5 Procedure	2
5.1 General	2
5.2 Conditioning method 82: Preconditioning of specimen and initial test	2
5.3 Conditioning methods 80 and 81: Pressure change curve	2
5.4 State of operation 2	3
5.5 Conditioning method 82: Recovery and final test	3
5.6 Conditioning method 82: Evaluation	3
6 Environmental test code	3
7 Specification	3
Annex A (informative) Explanatory notes	5