

ISO 9022-8:2015-03 (E)

Optics and photonics - Environmental test methods - Part 8: High internal pressure, low internal pressure, immersion

Contents		Page
Foreword		iv
Introduction		vi
1 Scope		1
2 Normative references		1
3 General information and test conditions		1
4 Conditioning		1
4.1 Conditioning method 80: High internal pressure.....		1
4.2 Conditioning method 81: Low internal pressure.....		1
4.3 Conditioning method 82: Immersion.....		2
5 Procedure		2
5.1 General.....		2
5.2 Conditioning method 82: Preconditioning of specimen and initial test.....		2
5.3 Conditioning methods 80 and 81: Pressure change curve.....		2
5.4 State of operation 2.....		3
5.5 Conditioning method 82: Recovery and final test.....		3
5.6 Conditioning method 82: Evaluation.....		3
6 Environmental test code		3
7 Specification		3
Annex A (informative) Explanatory notes		5