

ISO 9022-12:2015-04 (E)

Optics and photonics - Environmental test methods - Part 12: Contamination

Contents		Page
Foreword		iv
Introduction		vi
1	Scope	1
2	Normative references	1
3	General information and test conditions	1
3.1	Specimen	1
3.2	Test pad	2
3.3	Test weight and arrangement of test pads	3
4	Conditioning	4
4.1	General	4
4.2	Conditioning method 86: Basic cosmetic substances and artificial hand sweat	4
4.3	Conditioning method 87: Laboratory agents	4
4.4	Conditioning method 88: Production plant resources	4
4.5	Conditioning method 89: Fuels and resources for aircraft, naval vessels, and land vehicles	4
5	Procedure	7
5.1	General	7
5.2	Preconditioning	7
5.3	Test sequence	8
5.4	Recovery	8
5.5	Evaluation	8
5.6	General level for acceptance	8
6	Environmental test code	9
7	Specification	9
Annex A (normative)	Determination of pH value of aqueous extract of pad materials	10