

DIN EN 16128:2016-02 (E)

Ophthalmic optics - Reference method for the testing of spectacle frames and sunglasses for nickel release

Contents		Page
European foreword		4
Introduction		6
1	Scope	7
2	Normative references	7
3	Terms and definitions	7
4	Principle	8
5	Selection of test samples	8
6	Simulation of wear and corrosion	9
6.1	Preparation of test samples	9
6.2	Procedure	10
7	Coating test	10
7.1	General	10
7.2	Apparatus and consumables	10
7.3	Preparation of test samples for the coating test	11
7.3.1	Parts to be tested	11
7.3.2	Dismantling and/or cutting and/or masking	11
7.3.3	Determination of test area	13
7.3.4	Preparation of electrical contact area	13
7.4	Preparation of saline solution	13
7.5	Procedure	13
7.5.1	Preparation of the electro-chemical cell	13
7.5.2	Insertion and connection of the test part in the electro-chemical cell	14
7.5.3	Determination of open circuit potential and measurement of electrochemical impedance of test samples	14
7.5.4	Calibration and verification of the equipment	15
7.6	Calculation of results	15
7.6.1	General	15
7.6.2	Criteria for pass or fail of the test sample	15
7.7	Test report	15
8	Release of nickel and its quantitative analytical detection (migration test)	16
8.1	General	16
8.2	Apparatus and consumables	16
8.3	Preparation of test samples for the migration test	18
8.3.1	Parts to be tested	18
8.3.2	Guidance on selection of test areas on the parts to be tested	18
8.3.3	Dismantling and degreasing	19
8.4	Procedure	19
8.4.1	Preparation of test paper including determination of its area	19
8.4.2	Preparation of artificial sweat solution	20
8.4.3	Applying artificial sweat solution to the test paper and attaching it to the test sample	21
8.4.4	Blank sample	22
8.4.5	Incubation of test sample with test paper attached (release of nickel into paper)	22

8.4.6	Retrieval of the test paper from the test samples	22
8.4.7	Analysis of the test papers for nickel	22
8.5	Calculation of migration test results	24
8.6	Interpretation of migration test results	25
8.6.1	General	25
8.6.2	Assessment of compliance	25
8.7	Test report	25
Annex A (informative) Cutting and masking of test samples (Coating test)		27
A.1	Fronts	27
A.2	Sides (temples)	28
Annex B (normative) Selection of test areas and application of the test paper (Migration test)		29
B.1	General	29
B.2	Rims	29
B.3	Bridge	30
B.4	Brace bar	31
B.5	Sides	32
B.6	Trims	34
Bibliography		35