

ISO 13142:2015-07 (E)

Electro-optical systems - Cavity ring-down technique for high-reflectance measurement

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols used and units of measure	1
5	Test principles	2
5.1	General	2
5.2	Decay time of initial cavity and reflectance of cavity mirrors	2
5.3	Decay time of test cavity and reflectance of test sample	4
5.4	High reflectance measurement with an optical feedback CRD technique	4
6	Preparation of test sample and measurement arrangement	6
6.1	Test sample	6
6.2	Laser source	6
6.3	Ring-down cavity	6
6.4	Detection unit	6
6.5	Data acquisition and processing	7
6.6	Environment	7
7	Test procedure	7
7.1	General	7
7.2	Measurement of decay time of initial cavity	7
7.3	Calculation of reflectance of cavity mirrors	8
7.4	Measurement of decay time of test cavity	8
7.5	Calculation of reflectance of test sample	8
7.6	Assessments of the measurement	8
8	Main error factors	8
8.1	Influence of the instrumental response time on reflectance measurement	8
8.1.1	General	8
8.1.2	Multi-parameter fitting method	9
8.1.3	Data truncation method	9
8.2	Measurement error of the reflectance of cavity mirrors	10
8.3	Measurement error of the reflectance of test sample	10
9	Test report	10
Annex A (informative) Reflectance reliability check experiment		12
Annex B (informative) Test report		13
Bibliography		14