

ISO 10110-18:2018-12 (E)

Optics and photonics - Preparation of drawings for optical elements and systems - Part 18: Stress bi refraction, bubbles and inclusions, homogeneity, and striae

| Contents | | Page |
|--------------------|---|-------------|
| Foreword | | v |
| Introduction | | vi |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 3.1 | Terms for stress birefringence | 1 |
| 3.2 | Terms for bubbles and inclusions | 2 |
| 3.3 | Terms for homogeneity and striae | 2 |
| 4 | Specification of raw material and finished assemblies | 2 |
| 4.1 | Raw material | 2 |
| 4.2 | Finished assemblies | 2 |
| 5 | Stress birefringence | 3 |
| 5.1 | Principle of specification | 3 |
| 5.2 | Indication in drawings | 3 |
| 5.2.1 | Indication codes | 3 |
| 5.2.2 | Structure of the indication | 3 |
| 5.3 | Examples of indications for stress birefringence | 3 |
| 6 | Bubbles and inclusions | 3 |
| 6.1 | General | 3 |
| 6.2 | Principle of specification | 3 |
| 6.3 | Indication in drawings | 4 |
| 6.3.1 | Indication codes | 4 |
| 6.3.2 | Structure of the indication | 4 |
| 6.4 | Accumulation rule | 4 |
| 6.5 | Concentration rule | 5 |
| 6.6 | Examples of indications for bubbles | 5 |
| 7 | Homogeneity and striae | 5 |
| 7.1 | General | 5 |
| 7.2 | Indication in drawings | 5 |
| 7.2.1 | Indication codes | 5 |
| 7.2.2 | Structure of the indication | 6 |
| 7.3 | Homogeneity | 6 |
| 7.3.1 | Principle of specification | 6 |
| 7.3.2 | Quality classes | 6 |
| 7.3.3 | Focus term | 7 |
| 7.4 | Striae | 7 |
| 7.4.1 | Principles of specification | 7 |
| 7.4.2 | Density classes for striae | 7 |
| 7.4.3 | Wavefront deviation classes for striae | 7 |
| 7.4.4 | Comparison of density and wavefront quality classes for striae | 8 |
| 7.4.5 | Multiple orthogonal directions | 8 |
| 7.5 | Examples of indications for homogeneity and striae | 8 |

| | | |
|------|--|----|
| 8 | Indications for "no requirement" or "default" | 9 |
| 9 | Indications on drawings | 9 |
| 9.1 | Table field | 9 |
| 9.2 | Drawing field | 9 |
| 10 | Indications for other optical material tolerances | 9 |
| 11 | Examples of indications on drawings | 9 |
| 11.1 | Example 1: Raw material properties in the drawing region | 9 |
| 11.2 | Example 2: Finished part bubble specification | 10 |
| 11.3 | Example 3: Finished part, all three properties | 10 |
| 11.4 | Example 4: System example | 11 |
| 11.5 | Example 5: Tabulation example | 11 |
| | Annex A (informative) Stress optical constant and stress birefringence | 12 |
| | Annex B (informative) Guidance for stress birefringence in optical glass | 13 |
| | Annex C (informative) Guidance for bubble grades in optical glass | 15 |
| | Annex D (informative) Guidance for homogeneity in optical glass | 18 |
| | Annex E (informative) Guidance for striae in optical glass | 20 |
| | Bibliography | 22 |