

DIN ISO 10110-18:2019-09 (E)

Optics and photo nics - Preparation of drawings for optical elements and systems -
Part 18: Stress birefringence, bubbles and inclusions, homogeneity, and striae (ISO
10110-18:2018)

Contents

	Page
8 Indications for "no requirement" or "default"	16
9 Indications on drawings	16
9.1 Table field	16
9.2 Drawing field	16
10 Indications for other optical material tolerances	16
11 Examples of indications on drawings	16
11.1 Example 1: Raw material properties in the drawing region	16
11.2 Example 2: Finished part bubble specification	17
11.3 Example 3: Finished part, all three properties	17
11.4 Example 4: System example	18
11.5 Example 5: Tabulation example	18
Annex A (informative) Stress optical constant and stress birefringence	19
Annex B (informative) Guidance for stress birefringence in optical glass	20
Annex C (informative) Guidance for bubble grades in optical glass	22
Annex D (informative) Guidance for homogeneity in optical glass	25
Annex E (informative) Guidance for striae in optical glass	27
Bibliography	29