

ISO 13142:2021 (E)

Optics and photonics — Lasers and laser-related equipment — Cavity ring-down method for high-reflectance and high-transmittance measurements

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Symbols used and units of measure
5	Test principles
5.1	General
5.2	Decay time of initial cavity and reflectance of cavity mirrors
5.3	Decay time of test cavity and reflectance/transmittance of test sample
5.4	High reflectance/transmittance measurement with an optical feedback CRD technique
6	Preparation of test sample and measurement arrangement
6.1	Test sample
6.2	Laser source
6.3	Ring-down cavity
6.4	Detection unit
6.5	Data acquisition and processing
6.6	Environment
7	Test procedure
7.1	General
7.2	Measurement of decay time of initial cavity
7.3	Calculation of reflectance of cavity mirrors
7.4	Measurement of decay time of test cavity
7.5	Calculation of reflectance/transmittance of test sample
7.6	Assessments of the measurement
8	Main error factors
8.1	Influence of the instrumental response time on reflectance/transmittance measurement
8.1.1	General
8.1.2	Multi-parameter fitting method
8.1.3	Data truncation method
8.2	Measurement error of the reflectance of cavity mirrors
8.3	Measurement error of the reflectance/transmittance of test sample
9	Test report
Annex A	(informative) Reflectance/transmittance reliability check experiment
A.1	General
A.2	Method
Annex B	(informative) Test report