

DIN ISO 9211-4:2023-07 (E)

Optics and photonics - Optical coatings - Part 4: Specific test methods: abrasion, adhesion and resistance to water (ISO 9211-4:2022)

Contents		Page
National foreword		3
National Annex NA (informative) Bibliography		5
Foreword		6
1	Scope	7
2	Normative references	7
3	Terms and definitions	7
4	Preparation prior to testing	7
5	Abrasion tests: cheesecloth/eraser test (conditioning method 01)	8
5.1	General.....	8
5.2	Test conditions.....	8
5.2.1	General.....	8
5.2.2	Moderate abrasion test.....	8
5.2.3	Severe abrasion test.....	8
5.3	Degree of severity: abrasion – cheesecloth/eraser test (conditioning method 01).....	8
5.4	Recovery.....	9
5.5	Evaluation.....	9
6	Adhesion test: tape test (conditioning method 02)	9
6.1	General.....	9
6.2	Test conditions.....	9
6.3	Degree of severity: adhesion – tape test (conditioning method 02).....	10
6.4	Recovery.....	10
6.5	Evaluation.....	10
7	Adhesion test: crosshatch test (conditioning method 03)	10
7.1	General.....	10
7.2	Test conditions.....	10
7.3	Degree of severity.....	10
7.4	Conditioning.....	11
7.5	Recovery.....	11
7.6	Evaluation.....	11
8	Resistance to water: exposure to water (conditioning method 04)	11
8.1	General.....	11
8.2	Test conditions.....	11
8.3	Degree of severity: resistance to water – exposure to water (conditioning method 04).....	12
8.4	Recovery.....	12
8.5	Evaluation.....	12
9	Adhesion test: pull-off test (conditioning method 05)	13
9.1	General.....	13
9.2	Test conditions.....	13
9.3	Degree of severity: adhesion – pull-of test (conditioning method 05).....	14
9.4	Evaluation.....	14
10	Environmental test code	14

Annex A (normative) Materials for abrasion testing of optical coatings	15
Annex B (informative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings	18
Annex C (normative) Visual examination of optical coatings	20
Bibliography	21