

# DIN ISO 9211-4:2023-07 (E)

## Optics and photonics - Optical coatings - Part 4: Specific test methods: abrasion, adhesion and resistance to water (ISO 9211-4:2022)

---

| <b>Contents</b>   |   | <b>Page</b> |
|---|---|-------------|
| <b>National foreword</b> .....                            |   | <b>3</b>    |
| <b>National Annex NA (informative) Bibliography</b> ..... |   | <b>5</b>    |
| <b>Foreword</b> .....                                     |   | <b>6</b>    |
| <b>1</b>  | <b>Scope</b> .....  | <b>7</b>    |
| <b>2</b>  | <b>Normative references</b> .....   | <b>7</b>    |
| <b>3</b>  | <b>Terms and definitions</b> .....  | <b>7</b>    |
| <b>4</b>  | <b>Preparation prior to testing</b> .....   | <b>7</b>    |
| <b>5</b>  | <b>Abrasion tests: cheesecloth/eraser test (conditioning method 01)</b> .....             | <b>8</b>    |
| 5.1   | General.....  | 8           |
| 5.2   | Test conditions.....  | 8           |
| 5.2.1   | General.....  | 8           |
| 5.2.2   | Moderate abrasion test.....   | 8           |
| 5.2.3   | Severe abrasion test.....   | 8           |
| 5.3   | Degree of severity: abrasion – cheesecloth/eraser test (conditioning method 01).....      | 8           |
| 5.4   | Recovery.....   | 9           |
| 5.5   | Evaluation.....   | 9           |
| <b>6</b>  | <b>Adhesion test: tape test (conditioning method 02)</b> .....                            | <b>9</b>    |
| 6.1   | General.....  | 9           |
| 6.2   | Test conditions.....  | 9           |
| 6.3   | Degree of severity: adhesion – tape test (conditioning method 02).....                    | 10          |
| 6.4   | Recovery.....   | 10          |
| 6.5   | Evaluation.....   | 10          |
| <b>7</b>  | <b>Adhesion test: crosshatch test (conditioning method 03)</b> .....                      | <b>10</b>   |
| 7.1   | General.....  | 10          |
| 7.2   | Test conditions.....  | 10          |
| 7.3   | Degree of severity.....   | 10          |
| 7.4   | Conditioning.....   | 11          |
| 7.5   | Recovery.....   | 11          |
| 7.6   | Evaluation.....   | 11          |
| <b>8</b>  | <b>Resistance to water: exposure to water (conditioning method 04)</b> .....              | <b>11</b>   |
| 8.1   | General.....  | 11          |
| 8.2   | Test conditions.....  | 11          |
| 8.3   | Degree of severity: resistance to water – exposure to water (conditioning method 04)..... | 12          |
| 8.4   | Recovery.....   | 12          |
| 8.5   | Evaluation.....   | 12          |
| <b>9</b>  | <b>Adhesion test: pull-off test (conditioning method 05)</b> .....                        | <b>13</b>   |
| 9.1   | General.....  | 13          |
| 9.2   | Test conditions.....  | 13          |
| 9.3   | Degree of severity: adhesion – pull-of test (conditioning method 05).....                 | 14          |
| 9.4   | Evaluation.....   | 14          |
| <b>10</b>   | <b>Environmental test code</b> .....  | <b>14</b>   |

|   |           |
|---|-----------|
| <b>Annex A (normative) Materials for abrasion testing of optical coatings</b> .....   | <b>15</b> |
| <b>Annex B (informative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings</b> ..... | <b>18</b> |
| <b>Annex C (normative) Visual examination of optical coatings</b> .....   | <b>20</b> |
| <b>Bibliography</b> .....   | <b>21</b> |