

ISO 23701:2023-04 (E)

Optics and photonics - Laser and laser-related equipment - Photothermal technique for absorption measurement and mapping of optical laser components

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols used and units of measure	2
5	Test method	2
5.1	Test principle	2
5.1.1	General	2
5.1.2	Photothermal lensing (TL)	3
5.1.3	Photothermal deflection (PTD)	3
5.1.4	Rules for selecting reflected and transmitted photothermal detection schemes	3
5.2	Measurement arrangement and test equipment	3
5.2.1	Photothermal detection arrangement	3
5.2.2	Pump laser	6
5.2.3	Probe laser	6
5.2.4	Translation stage	6
5.2.5	Detection unit	7
5.2.6	Data acquisition and processing	7
5.2.7	Environment	7
5.3	Preparation of test sample	7
6	Test procedure	7
6.1	General	7
6.2	Measurements of photothermal amplitude and phase	8
6.3	Maps of photothermal amplitude and phase	8
6.4	Calibration of photothermal amplitude	9
6.5	Assessments of the measurement	10
7	Evaluation	11
7.1	Determination of absorption via photothermal measurement	11
7.2	Determination of absorptance via photothermal calibration	12
7.3	Two-dimensional/three-dimensional maps of absorption	13
7.4	Mapping area and spatial resolution	13
8	Test report	14
Annex A (informative) Theoretical and practical considerations on calibration		16
Annex B (informative) Separation of surface absorption and bulk absorption		18
Annex C (informative) Test report		21
Bibliography		22