

# DIN EN 12472:2006-03 (E)

## Method for the simulation of wear and corrosion for the detection of nickel release from coated items

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Principle .....	5
4	Reagents and materials .....	5
4.1	Corrosion .....	5
4.2	Wear .....	6
5	Procedure .....	8
5.1	Sample preparation .....	8
5.2	Corrosion procedure .....	8
5.3	Wear procedure .....	8
5.4	Determination of nickel release .....	9
6	Test report .....	9
Annex A (informative) Detailed examples of how to attach different types of items .....		10
A.1	General .....	10
A.2	Attachment of items with only one side in contact with the skin .....	10
A.3	Spectacle frames .....	10
A.4	Chains, watches, bracelets, rings etc .....	12
Bibliography .....		14