

# ISO 15004-2:2007-02 (E)

## Ophthalmic instruments - Fundamental requirements and test methods - Part 2: Light hazard protection

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions and symbols .....</b>	<b>1</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.2</b>	<b>Symbols .....</b>	<b>5</b>
<b>4</b>	<b>Classification .....</b>	<b>6</b>
<b>5</b>	<b>Requirements .....</b>	<b>6</b>
<b>5.1</b>	<b>General .....</b>	<b>6</b>
<b>5.2</b>	<b>Requirements for classification as a Group 1 instrument .....</b>	<b>6</b>
<b>5.3</b>	<b>Requirements for Group 2 instruments .....</b>	<b>7</b>
<b>5.4</b>	<b>Emission limits for determination of Group 1 classification .....</b>	<b>7</b>
<b>5.5</b>	<b>Emission limits and guideline values for Group 2 instruments .....</b>	<b>11</b>
<b>6</b>	<b>Test methods .....</b>	<b>16</b>
<b>6.1</b>	<b>General .....</b>	<b>16</b>
<b>6.2</b>	<b>Measurements made to classify instruments into Group 1 or Group 2 .....</b>	<b>16</b>
<b>6.3</b>	<b>Group 2 instruments: Measurements .....</b>	<b>16</b>
<b>6.4</b>	<b>Determination of area .....</b>	<b>17</b>
<b>6.5</b>	<b>Group 2 instruments: Determination of time and number of pulses to reach maximum exposure guidelines .....</b>	<b>17</b>
<b>7</b>	<b>Information supplied by the manufacturer .....</b>	<b>18</b>
<b>Annex A (normative) Spectral weighting functions .....</b>		<b>20</b>
<b>Annex B (informative) Product-related International Standards for ophthalmic instruments to Annex C (informative) Measurement instruments .....</b>		<b>27</b>
<b>Annex D (normative) Measurement methods for radiance/irradiance .....</b>		<b>28</b>
<b>Annex E (informative) Guidance on the direct measurement of irradiance .....</b>		<b>33</b>
<b>Annex F (informative) Classification flowchart .....</b>		<b>35</b>
<b>Bibliography .....</b>		<b>37</b>